UNCLASSIFIED

AD 402 731

Reproduced by the

DEFENSE DOCUMENTATION CENTER

FOR


SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION, ALEXANDRIA, VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.



DEVELOPMENT OF AN IMPROVED JAN 6299

Report No. 5

Fifth Quarterly Progress Report

17 September 1962 through 31 December 1962

CONTRACT NO. DA-36-039-SC-85953

ORDER 6008-PP-61-81-81

Industrial Preparedness Group USASSA Philadelphia, Pennsylvania



RECEIVING TUBE DEPARTMENT

GENERAL ELECTRIC
OWENSBORO, KENTUCKY

DEVELOPMENT OF AN IMPROVED JAN 6299

Report No. 5

Fifth Quarterly Progress Report

17 September 1962 through 31 December 1962

- OBJECTIVE: (1) To obtain better performance and greater reliability from the JAN 6299 by evaluating and adapting the latest tube technological advancements.
 - (2) To build 1000 tubes capable of passing Signal Corps Technical Requirements SCS-90 dated 1 July 1960.

CONTRACT NO. DA-36-039-SC-85953

SIGNAL CORPS INDUSTRIAL PREPAREDNESS
PROCUREMENT REQUIREMENTS (Scipper) No. 15
1 October 1958

SCS-90, 1 July 1960

TABLE OF CONTENTS

| TITLE | PAGE |
|---|------|
| PURPOSE | 1 |
| ABSTRACT | 2 |
| MARRATIVE | 3 |
| CONCLUSIONS | 25 |
| PROGRAM FOR MEXT INTERVAL | 27 |
| PUBLICATIONS, LECTURES, REPORTS AND COMPERENCES | 29 |
| PERSCHUEL | 31 |
| APPENDIX - Biography | 32 |
| ADDENNITY - Deinte | 22 |

LIST OF ILLUSTRATIONS

| PIGURE | | PAGE |
|--------|------------------------------------|------|
| 1 | Trial Exhaust and Sealing Cycles | 6 |
| 2 | Improved JAN 6299 Project Schedule | 26 |

LIST OF TABLES

| TABLE | | PAGE |
|-------|--|-------|
| I | Results of Trial Sealing Schedules | 7 |
| II . | High Temperature Life 225°C Anode Temperature | 10 |
| III | Mass Spectrometric Gas Content Analysis of 6299 Tube | 13 |
| IA | Humidity Test Results | 14 |
| ٧ | 100°C Oven Tests | 21-22 |

PURPOSE

The purpose of this contract is to evaluate certain areas of advanced tube manufacturing techniques and apply them where feasible to JAH 6299 to result in a more reliable and better performing tube. The objective requirements for the improved tube are Signal Corps Technical Requirement SCS-90 (Improved JAH 6299) and operation at a tube temperature rating of 225°C. The areas under investigation are:

- 1. Improved alignment, concentricity and ceramic strength.
- 2. Improved anode to ceramic seal.
- 3. Temperature control at exhaust.
- 4. Improved application of cathode coating.
- 5. Improved cathode mounting.
- 6. Improve processing for higher temperature operation.
- 7. Improvement in humidity testing.
- 8. Improved exhaust fixturing.
- 9. Extended life test and tube failure analysis.

ABSTRACT

The status of each of the nine projects is summarized. A mass spectrometric gas content analysis is given of SCS-90 humidity test failures.

NARRATIVE

PROJECT I IMPROVED ALIGNMENT CONCENTRICITY AND CERAMIC STRENGTH

In an effort to improve the alignment and concentricity of the tube, the ceramics and metal parts have been made to tighter tolerences. The ceramic composition has been changed from forsterite to 96% alumina in the heater, getter, and anode ceramics for greater strength. The cathode ceramic, when changed to 96% alumina, produced a median Cgk of 4.81 mmf. This data is given on pages 11, 12 and 13 of the Third Quarterly Progress Report. This is an increase of 31.8% over the bogy value of 3.65 mmf. Redesign of the cathode ceramic to compensate for a change of this magnitude, it is felt would be a major design change.

The improvements made in this project should enable improved exhaust fixturing (Project 9) to further improve alignment and concentricity of the tube. Project I is complete.

PROJECT II SEAL REDESIGN

a) Anode Seal

The copper anode is butt sealed to the 96% alumina ceramic with silver-copper eutectic. If care is taken when the ceramic metallizing is done, the Cgp centers near bogy. Continued life test of the two tubes whose 1000 hour life test data is in the Fourth Quarterly Progress Report showed a failure of 1000 hour life test limits after 4911 and 6035 hours.

b) Getter Shell and Cathode Shell Seals

The present is butt sealed with silver-copper eutectic and the ceramic is 96% alumina. No assembly problems are evident. Five tubes with hard solder anode seals and hard solder presents passed 1000 hour life test limits for 3185, 3429, 4023, 4023 and 5147 hours.

This project is complete.

PROJECT III TEMPERATURE CONTROL AT EXHAUST

The temperature control equipment was moved from Scranton and installed at Owensboro. Shortly after installation, a component failed. This was repaired and the equipment was adjusted and used to monitor production exhaust schedules in order to determine some trial sealing schedules.

Tubes were exhausted to 5 trial sealing schedule, which are shown in Graph I. Exhaust results are shown in Table I. Runs 1 and 5 exhibited excessive lead flow from too much heat, which resulted in shorts. Runs 3 and 4 were too cold for good lead flow, causing high leaker shrinkage. Run 2, which closely approximates the present processing showed the most promise. Repeatibility of the equipment in reproducing the set program seems quite good. On the basis of the results obtained, the temperature controller will be used to produce sustained runs of tubes with the present processing.

The equipment will be connected so that 2 exhaust sets will have the temperature controlled by same temperature controller. The exhaust sets are connected so that one bombarder supplies the r-f energy to 2 sets. When this is accomplished successfully, another temperature controller will be installed to control the sealing cycles of the 2" remaining exhaust sets.






TABLE I

Results of Trial Sealing Schedules

| Heating Schedule | No. Tubes | Exhaust Shrinkage |
|---------------------|--------------|----------------------|
| 1 | 14 | 35.7% |
| 2 | 28 | 3.6% |
| 3 | 28 | 21.4% |
| 4 | 21 | 19.0% |
| 5 | 28 | 35.7% |

PROJECT IV OPTIMIZE CATHODE COATING

The Paasche A - Automatic spray gun along with the improved spray fixtures continue to give uniform results in production. The spray density life tests indicated for favorable life test results, the density should be greater than 1.0 mg/mm³. Cathode spray density has been adjusted from 0.9 - 1.05 mg/mm³ to 1.25 - 1.35 mg/mm³ on production tubes. The 1.25 - 1.35 mg/mm³ density gave good life test results and is easier to activate than the higher density groups. The spraying of the higher cathode densities are also more difficult to control in production with the present cathode spray equipment. In view of data derived in this test, coupled with manufacturing experience, it is felt that the 1.25 - 1.35 mg/mm³ density group will greatly improve the quality of the tube.

This project is complete.

PROJECT V IMPROVED CATHODE MOUNTING

No work was scheduled in this work period. In the next quarter tubes will be made with various cathode foil thickness and the cathode temperature will be determined. This will enable the correct thickness of cathode foil to be selected to give the proper cathode temperature for good life test results.

PROJECT VI IMPROVED PROCESSING FOR HIGHER TEMPERATURE OPERATION

a) Life Test

Seventeen (17) production tubes were run at 225°C anode temperature on the high temperature life rack. Within 24 hours 11 tubes became air leakers and 3 tubes developed open heaters due to burning open in air. The lot was discontinued and an adapter was made to determine where the leaks developed. This analysis disclosed all leaks were at the anode seal.

Seven (7) tubes with hard solder anode seals and hard solder preseals were put on high temperature life with the anode temperature at 225°C. These tubes demonstrated the hard solder anode is a much improved seal as 6 tubes were good at 129 hours. One tube failed as a grid to plate short in less than 8 hours. Electrical data is clouded by a high cathode temperature in these tubes. The data for these tubes is given in Table II.

b) Plating

The seven (7) tubes with hard solder seals had severe plating deterioration at 129 hours. The next lot of tubes that is run on high temperature life will have a nickle plating under the gold to prevent gold migration. The connections of the life rack itself corroded and these will be likewise nickle-gold plated.

TABLE II

High Temperature Life 225°C Anode Temperature

| | | 2 | HOURS | | | |
|----------|-----|------|-------|----|-------|------|
| Tube No. | If | EC | Is | Eb | Noise | Gain |
| 1 | 301 | 1.13 | 12.0 | 65 | 8.0 | 18.1 |
| 2 | 300 | 0.97 | 10.6 | 77 | 8.3 | 17.6 |
| 3 | 305 | 0.90 | 10.5 | 84 | 8.5 | 17.1 |
| 4 | 301 | 2.10 | 15.0 | 49 | 10.2 | 14.4 |
| 5 | 308 | 0.78 | 10.4 | 83 | 8.1 | 18.1 |
| 6 | 301 | 0.81 | 12.0 | 65 | 8.0 | 17.7 |
| 7 | 301 | 0.44 | 8.0 | 95 | 8.5 | 1777 |

129 HOURS

| Tube No. | <u>If</u> | Ec | <u>Is</u> | <u>P</u> b | Noise | Gain |
|----------|-----------|------|-----------|------------|---------------------------------------|------|
| 1 | 300 | 1.40 | 14.0 | 60 | 8.0 | 17.8 |
| 2 | 302 | 1.02 | 10.7 | 90 | 8.3 | 17.4 |
| 3 | 305 | 1.06 | 11.3 | 90 | 8.3 | 17.3 |
| 4 | 303 | 2.46 | 17.0 | 40 | 10.5 | 13.3 |
| 5 | | G | - P Sho | rt - | · · · · · · · · · · · · · · · · · · · | |
| 6 | 305 | 1.02 | 11.6 | 80 | 8.0 | 17.8 |
| 7 | 301 | 0.68 | 8.5 | 100 | 8.3 | 17.2 |

Tubes with hard solder anode, hard solder preseal, regular plating, and high cathode temperature.

PROJECT VII IMPROVEMENT IN HUMIDITY TESTING

A mass spectrometric gas content analysis was performed on tubes that failed during humidity test. Sample analysis was performed as follows:

- Each tube was cleaned with acetone and mounted in a device which could break it under vacuum. The breaker was also cleaned in acetone.
- 2. The breaker device was evacuated for 2-4 hours, depending on background. The breaker was also heated for several minutes during the early stages of evacuation.
- 3. The tube was then punctured and, while monitoring hydrogen and nitrogen, the sample gases were collected until these peaks reached a maximum.

The volume of the tube was determined by puncturing a number of good tubes under water and converting the weight of the water pulled into the tube into milliliters. The volume of the tube was calculated to be 0.15 ml and the volume of the mass spectrometer collection system was calculated to be 3.3 liters. The internal pressures should not be taken as exact pressures but treated as estimates. These results are shown in Table III.

The gas analysis confirmed that extremely high heater currents are due to the presence of hydrogen in the tube. Tubes 1, 2,

3. 4. 7, and 8 were tested soon after removal from the humidity test chamber. Tube 5 had been out of the humidity test chamber for about 5 months and tube 6 had been removed from the chamber for approximately 3 weeks. The extremely high pressure exhibited by tube 6 would tend to indicate a generation of hydrogen due to corrosion.

Tubes baked at 100°C in an oven did not show any failures. These tests were performed to eliminate the possibility of internal hydrogen generation as a cause of failure.

One test run of GL-7391's were performed. These have the same external parts as the JAN 6299 and results were comparable.

Tubes with part of the titanium hydride replaced with titanium powder were examined. This was done to decrease the amount of hydrogen released at exhaust. Poor seals were obtained due to poor wetting of the lead. The good tubes when submitted to the humidity test showed no improvement over production tubes.

Tubes with nickle-gold and copper-nickle-gold plating were humidity tested. The gold plating was immersion gold. The nickle gold plating look somewhat better than normal production; however, due to the failure rate of the copper-nickle-gold plated tubes, a re-evaluation of these results are necessary.

Results from humidity tests are found in Table IV.

Results from 100°C oven test and 100°C oven test vs. humidity test are found in Table V.

TABLE III

Mass Spectrometric Gas Content Analysis of 6299 Tube

| Notes | | rupe passed humidity test | Humidity test | failure 4 days | Tube #7 from | humidity test | 11-16-62 | Tube #8 from | humidity test | 11-16-62 | Tube from Eng. | sample humidity | test | Tube from humidity | test of GL-7391 | Tube #17 from | humidity test | 11-16-62 | Tube #5 from | humidity test | 79-91-11 |
|-------------------------------|-----------------|------------------------------|---------------|----------------|---------------------|---------------|----------|---------------------|---------------|----------|---------------------|-----------------|------|----------------------|----------------------|---------------------|---------------|----------|----------------------|---------------|----------|
| Pressure mm H _G | | ı | 762 | | 167 | | | 333 | | | 272 | | | 1902 | | 312 | | | 163 | | |
| ~ | | ı | ı | | 1 | | | 0.08 | | | 0.15 | | | 0.10 0.10 | | 1.10 | | | 1.10 | | |
| E E | İ | J | 0.52 | | 0.16 | | | 0.60 | | | 0.15 0.15 | | | 0.10 | | 0.45 1.10 | | | 0.40 1.10 | | |
| 07 | | 1 | ı | | ı | | | ı | | | ı | | | ı | | 16.5 | | | 20.5 | | |
| M 2 | | l | 0.23 | | 2.64 | | | 7.05 | | | 24.3 | | | 30.6 | | 81.6 | | | 6.77 | | |
| 표 | | ì | 99.3 | | 97.2 | | | 92.0 7.05 | | | 75.2 24.3 | | | 68.9 30.6 | | ı | | | ı | | |
| Collection Time (Min.) | | 4 | н | | 7 | | | ო | | | m | | | 35 | | 8 | | | 7 | | |
| If (ma) | 010 010 010 010 | 015-015-015-015 | 320-600+ | | 310-310-310-310-750 | | | 315-315-315-600-740 | | | 315-305-720-770-750 | | | 385-560-770-800-710) | 710-700-700-700-650) | 315-560-510-500-500 | , | ; | 3104310-310-6004-510 | | |
| Tube No. | - | 4 | 7 | | က | | | 4 | | | ហ | | ı | Φ | | M | | | œ | | |

Performed by:

B.I. Grady, Jr. Chemical & Physics Laboratory Advanced Development Eng.

TABLE IV
Humidity Test of SCS-90

All heater current readings are in milliamperes 10% allowable increase in $\mathbf{I}_{\mathbf{f}}$

6299 Engineering Samples
Tubes with 3 Hard Solder Seals
(Interrupted Humidity Test)

| | E /10 | E /22 | 0.70 | 0/17 |
|--------|-------|-------|------|------|
| Date | 5/18 | 5/23 | 8/9 | 8/17 |
| Days | 0 | 5 | 5 | 13 |
| Tube N | io. | | | |
| 1 | 309 | 400 | 670 | 650 |
| 2 | 310 | 435 | 475 | 470 |
| 3 | 311 | 490 | 515 | 505 |
| 4 | 311 | 440 | 565 | 650 |
| 5 | 314 | 304 | 305 | 290 |
| 6 | 315 | 305 | 720 | 770 |
| 7 | 313 | 303 | 295 | 295 |
| 8 | 310 | 435 | 430 | 720 |
| 9 | 313 | 304 | 300 | 295 |

% Rejects = 6/9 = 66%

6299 (Scranton Production)

Lot W/B 62-11

| Days | 0 | 4 | 10 | 14 | 18 | 21 | 34 | 56 | 53 | 58 |
|--------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| Tube N | io. | | | | | | | | | |
| 1 | 300 | 290 | 285 | 285 | 290 | 290 | 290 | 290 | 300 | 290 |
| 2 | 290 | 290 | 291 | 290 | 290 | 290 | 290 | 290 | 300 | 290 |
| 3 | 300 | 295 | 290 | 290 | 290 | 290 | 290 | 290 | 300 | 290 |
| 4 | 290 | 290 | 285 | 285 | 285 | 285 | 285 | 285 | 300 | 290 |
| 5 | 290 | 450 | 548 | 575 | 595 | 595 | 560 | 560 | 560 | 585 |
| 6 | 300 | 300 | 524 | 530 | 530 | 530 | 530 | 530 | 530 | 530 |
| 7 | 300 | 720 | 639 | 480 | 470 | 470 | 480 | 460 | 460 | 460 |
| 8 | 290 | 290 | 290 | 290 | 290 | 290 | 290 | 290 | 300 | 290 |
| 9 | 310 | 305 | 320 | 360 | 670 | 700 | 700 | 700 | 700 | 700 |
| 10 | 290 | 290 | 290 | 290 | 290 | 295 | 700 | 700 | 700 | 700 |
| 11 | 290 | 290 | 695 | 720 | 750 | 700 | 660 | 475 | 475 | 460 |
| 12 | 300 | 300 | 298 | 298 | 298 | 290 | 290 | 290 | 300 | 290 |
| 13 | 290 | 290 | 281 | 280 | 280 | 280 | 280 | 280 | 290 | 280 |
| 14 | 290 | 290 | 328 | 429 | 490 | 515 | 590 | 600 | 600 | 620 |
| 15 | 300 | 295 | 290 | 290 | 290 | 290 | 290 | 290 | 290 | 290 |
| 16 | 290 | 290 | 320 | 730 | 760 | 750 | 710 | 690 | 690 | 710 |

% rejects = 7/16 = 44%

GL-7391 (Scranton Production)

Lot W/E 62-15

| Days | 0 | 2 | 6 | 9 | 13 | 16 | 18 | 27 | 44 |
|--------|-------|-----|-----|-----|-----|-----|-----|-------------|-----|
| Tube 1 | io. | | | | | | | | |
| 1 | 380 | 385 | 385 | 380 | 380 | 380 | 380 | 380 | 380 |
| 2 | 382 | 385 | 385 | 390 | 390 | 380 | 380 | 600 | 650 |
| 3 | 386 | 385 | 385 | 385 | 385 | 380 | 380 | 380 | 380 |
| 4 | 380 | 380 | 380 | 380 | 380 | 380 | 380 | 380 | 380 |
| 5 | 385 | 385 | 385 | 380 | 380 | 380 | 380 | 500 | 490 |
| 6 | 390 | 390 | 395 | 390 | 390 | 390 | 390 | 750 | 650 |
| 7 | 388 | 390 | 390 | 380 | 380 | 380 | 380 | 380 | 650 |
| 8 | 380 | 380 | 380 | 380 | 380 | 380 | 380 | 380 | 390 |
| 9 | 385 | 720 | 570 | 590 | 650 | 650 | 600 | 600 | 600 |
| 10 | 382 | 380 | 380 | 380 | 380 | 380 | 380 | 700 | 700 |
| 11 | 382 | 380 | 490 | 710 | 760 | 760 | 750 | 700 | 700 |
| 12 | 380 | 380 | 380 | 380 | 380 | 380 | 380 | 390 | 600 |
| 13 | 385 | 385 | 385 | 380 | 380 | 380 | 380 | 750 | 700 |
| 14 | 390 | 800 | 730 | 830 | 700 | 700 | 700 | 700 | 700 |
| 15 | 390 | 390 | 390 | 390 | 390 | 385 | 390 | 390 | 400 |
| 16 | 385 | 385 | 385 | 390 | 390 | 390 | 380 | 390 | 390 |
| 17 | 385 | 385 | 385 | 380 | 380 | 380 | 380 | 380 | 380 |
| 18 | 385 | 560 | 770 | 800 | 710 | 710 | 700 | 70 0 | 700 |
| 19 | 380 | 380 | 380 | 380 | 380 | 380 | 380 | 390 | 700 |
| 20 | 385 | 385 | 385 | 385 | 590 | 600 | 600 | 600 | 600 |
| 21 | 385 | 380 | 380 | 380 | 380 | 380 | 380 | 390 | 700 |
| 22 | 405 | 405 | 405 | 605 | 870 | 800 | 800 | 750 | 750 |
| 23 | . 385 | 385 | 385 | 380 | 380 | 380 | 380 | 380 | 390 |
| 24 | 370 | 370 | 370 | 370 | 370 | 370 | 370 | 370 | 380 |
| 25 | 400 | 400 | 400 | 400 | 400 | 400 | 400 | 405 | 480 |
| 26 | 388 | 390 | 390 | 385 | 385 | 800 | 800 | 800 | 700 |
| 27 | 385 | 385 | 840 | 825 | 820 | 800 | 750 | 750 | 700 |

% Rejects = 8/27 = 30%

6299 (Owensboro Production)

Lot W/E 62-46

| Days | 0 | 3 | 7 | 11 | 14 |
|--------|-----|-----|-----|------|-----|
| Tube ! | No. | | | | |
| 1 | 310 | 310 | 310 | 310 | 310 |
| 2 | 310 | 310 | 310 | 310 | 310 |
| 3 | 310 | 310 | 310 | 310 | 310 |
| 4 | 310 | 310 | 310 | 310 | 310 |
| 5 | 310 | 310 | 310 | 600+ | 510 |
| 6 | 312 | 312 | 312 | 312 | 310 |
| 7 | 310 | 310 | 310 | 310 | 750 |
| 8 | 315 | 315 | 315 | 600+ | 740 |
| 9 | 310 | 310 | 310 | 310 | 310 |
| 10 | 320 | 320 | 320 | 320 | 320 |
| 11 | 312 | 312 | 312 | 312 | 310 |
| 12 | 310 | 310 | 310 | 310 | 310 |
| 13 | 320 | 320 | 320 | 320 | 390 |
| 14 | 300 | 310 | 320 | 600+ | 695 |
| 15 | 320 | 320 | 320 | 320 | 320 |
| 16 | 310 | 310 | 310 | 310 | 310 |
| 17 | 315 | 560 | 510 | 500 | 500 |
| 18 | 315 | 315 | 315 | 315 | 370 |
| 19 | 320 | 320 | 320 | 320 | 320 |
| 20 | 315 | 315 | 315 | 315 | 315 |

% rejects = 7/20 = 35%

6299 (Owensboro Production)

Lot W/E 62-46

| Days | 0 | 3 | 7 | 11 | 14 |
|--------|-----|-----|-----|------|-----|
| Tube 1 | No. | | | | |
| 1 | 310 | 310 | 310 | 310 | 310 |
| 2 | 310 | 310 | 310 | 310 | 310 |
| 3 | 310 | 310 | 310 | 310 | 310 |
| 4 | 310 | 310 | 310 | 310 | 310 |
| 5 | 310 | 310 | 310 | 600+ | 510 |
| 6 | 312 | 312 | 312 | 312 | 310 |
| 7 | 310 | 310 | 310 | 310 | 750 |
| 8 | 315 | 315 | 315 | 600+ | 740 |
| 9 | 310 | 310 | 310 | 310 | 310 |
| 10 | 320 | 320 | 320 | 320 | 320 |
| 11 | 312 | 312 | 312 | 312 | 310 |
| 12 | 310 | 310 | 310 | 310 | 310 |
| 13 | 320 | 320 | 320 | 320 | 390 |
| 14 | 300 | 310 | 320 | 600+ | 695 |
| 15 | 320 | 320 | 320 | 320 | 320 |
| 16 | 310 | 310 | 310 | 310 | 310 |
| 17 | 315 | 560 | 510 | 500 | 500 |
| 18 | 315 | 315 | 315 | 315 | 370 |
| 19 | 320 | 320 | 320 | 320 | 320 |
| 20 | 315 | 315 | 315 | 315 | 315 |

% rejects = 7/20 = 35%

6299 (Owensboro Production)

Part of Titanium Hydride replaced with Titanium Powder

| Days | 0 | 4 | 8 | 11 | 14 |
|----------|-----|-------|-----|------|------------------|
| Tube No. | | | | | |
| 1 | 310 | 315 | 315 | 315 | 315 |
| 2 | 317 | 317 | 317 | 320 | 320 |
| 3 | 317 | 317 | 317 | 320 | 320 |
| 4 | 315 | 315 | 320 | 320 | 320 |
| 5 | 320 | 320 | 325 | 320 | 360 |
| 6 | 319 | 500 | 590 | 590 | 640 |
| 7 | 320 | 320 | 320 | 320 | 320 |
| 8 | 318 | 318 | 320 | 320 | 320 |
| 9 | 311 | 310 | 312 | 310 | 310 |
| 10 | 310 | 310 | 312 | 330 | 320 |
| 11 | 312 | 312 | 310 | 310 | 340 |
| 12 | 320 | 600+* | | | |
| 13 | 315 | 520 | 530 | 540 | 540 |
| 14 | 320 | 320 | 320 | 320 | 750+ |
| 15 | 319 | 320 | 320 | 390 | 750+ |
| 16 | 325 | 325 | 750 | 750+ | 750 + |

^{*} Removed for Gas Analysis

% rejects = 8/16 = 50%

6299 (Owensboro Production)
light nickle plate and immersion gold plate

| Day | 0 | 4 | 7 | 11 | 14 | 17 | 24 | 45 |
|----------|-----|------|-----|-----|-----|-----|------------------|------|
| Tube No. | | | | | | | | |
| 1 | 312 | 315 | 315 | 315 | 315 | 315 | 315 | 315 |
| 2 | 312 | 320 | 320 | 320 | 320 | 320 | 320 | 320 |
| 3 | 315 | 320 | 320 | 320 | 320 | 320 | 320 | 320 |
| 4 | 319 | 750+ | 550 | 510 | 510 | 510 | 510 | 510 |
| 5 | 319 | 320 | 320 | 320 | 320 | 320 | 320 | 320 |
| 6 | 310 | 320 | 320 | 320 | 320 | 320 | 320 | 320 |
| 7 | 400 | 340 | 320 | 320 | 320 | 320 | 750 + | 540 |
| 8 | 305 | 315 | 315 | 315 | 315 | 315 | 315 | 320 |
| 9 | 315 | 320 | 320 | 320 | 320 | 320 | 320 | 320 |
| 10 | 310 | 320 | 320 | 310 | 320 | 320 | 320 | 320 |
| 11 | 312 | 320 | 320 | 320 | 320 | 320 | 320 | 750+ |

% rejects = 1/11 = 9%

| 6299 | Owens | boro 1 | Prod | <u>luction)</u> |
|------|-------|--------|------|-----------------|
| | | | | |

| | heavy | nickl | e plate | and in | mmersion | gold | plate | |
|----------|-------|------------------|---------|------------------|------------------|------|-------|------------------|
| Day | 0 | 4 | 7 | 11 | 14 | 17 | 24 | 45 |
| Tube No. | | | | | | | | |
| 1 | 315 | 325 | 325 | 320 | 320 | 320 | 320 | 320 |
| 2 | 310 | 315 | 310 | 320 | 320 | 320 | 320 | 750+ |
| 3 | 315 | 320 | 320 | 320 | 320 | 320 | 320 | 660 |
| 4 | 315 | 320 | 320 | 320 | 320 | 330 | 320 | 570 |
| 5 | 315 | 320 | 320 | 320 | 320 | 320 | 320 | 320 |
| 6 | 320 | 325 | 330 | 330 | 330 | 330 | 320 | 320 |
| 7 | 320 | 320 | 320 | 320 | 320 | 330 | 320 | 320 |
| 8 | 310 | 340 | 360 | 750+ | 750+ | 750+ | 750÷ | 750 + |
| 9 | 310 | 750 + | 750+ | 750 + | 750 + | 750+ | 750+ | 750+ |
| 10 | 320 | 325 | 325 | 325 | 325 | 325 | 325 | 330 |

% rejects = 2/10 = 20%

6299 (Owensboro Production)

light copper plate, light nickle plate, and immersion gold plate

| Day | 0 | 4 | 7 | 11 | 14 | 17 | 24 |
|----------|-----|------|-----|-----|------|------|------|
| Tube No. | | | | | | | |
| 1 | 310 | 320 | 320 | 320 | 470 | 470 | 470 |
| 2 | 315 | 320 | 320 | 320 | 320 | 320 | 320 |
| 3 | 309 | 320 | 320 | 320 | 320 | 320 | 460 |
| 4 | 315 | 325 | 325 | 325 | 500 | 620 | 620 |
| 5 | 315 | 750+ | 500 | 500 | 500 | 500 | 500 |
| 6 | 312 | 325 | 325 | 325 | 750+ | 750+ | 750+ |
| 7 | 315 | 320 | 320 | 320 | 320 | 320 | 670 |
| 8 | 314 | 320 | 320 | 310 | 320 | 320 | 360 |
| 9 | 315 | 320 | 320 | 320 | 320 | 320 | 520 |
| 10 | 320 | 325 | 325 | 325 | 325 | 325 | 740 |

% rejects = 4/10 = 40%

6299 (Owensboro Production)

heavy copper plate, heavy nickle plate, and immersion gold plate

| Day | 0 | 4 | 7 | 11 | 14 | 17 | 24 |
|----------|-----|-----|------|------|------|------|------|
| Tube No. | | | | | | | |
| 1 | 320 | 325 | 750+ | 645 | 600 | 600 | 620 |
| 2 | 310 | 320 | 310 | 750+ | 700 | 520 | 640 |
| 3 | 335 | 340 | 680 | 700 | 750+ | 720 | 720 |
| 4 | 315 | 380 | 650 | 750+ | 750+ | 750 | 750 |
| 5 | 315 | 325 | 325 | 325 | 325 | 320 | 350 |
| 6 | 320 | 330 | 330 | 320 | 320 | 320 | 320 |
| 7 | 320 | 320 | 320 | 320 | 320 | 600 | 520 |
| 8 | 320 | 325 | 325 | 325 | 325 | 325 | 700 |
| 9 | 322 | 320 | 320 | 320 | 330 | 325 | 325 |
| 10 | 324 | 330 | 330 | 330 | 330 | 750+ | 750+ |

% rejects = 4/10 = 40%

TABLE V

81.

6299 (Scranton Production)

W/E 62-01

baked in oven 100°C

| Days | 0 | 1 | 7 | 15 | 21 |
|----------|-----|-----|-----|-----|-----|
| Tube No. | | | | | |
| 1 | 315 | 315 | 315 | 315 | 315 |
| 2 | 320 | 320 | 320 | 318 | 320 |
| 3 | 320 | 320 | 315 | 315 | 320 |
| 4 | 318 | 320 | 320 | 320 | 320 |
| 5 | 310 | 315 | 312 | 312 | 315 |
| 6 | 320 | 320 | 320 | 320 | 320 |
| 7 | 320 | 320 | 320 | 320 | 320 |
| 8 | 319 | 320 | 317 | 320 | 320 |
| 9 | 318 | 320 | 315 | 320 | 320 |
| 10 | 315 | 315 | 315 | 315 | 315 |
| 11 | 315 | 315 | 315 | 315 | 315 |
| 12 | 320 | 320 | 318 | 320 | 320 |

% rejects = 0/12 = 0%

6299 (Owensboro Production

Double Thickness of gold plating

| | SCS-9 Humidit | | | 100 | _ |
|------------------|------------------|------------------|------------------|---------|------|
| | 11dhiLd1 | y rest | | In | Oven |
| Days Tube No. | 0 | 6 | Days Tube No. | 0 | 8 |
| 1 | 318 | 750 + | 1 | 320 | 320 |
| 2 | 320 | 660 | 2 | 320 | 320 |
| 3 | 320 | 630 | 3 | 320 | 320 |
| 4 | 330 | 330 | 4 | 330 | 325 |
| 5 | 325 | 750 | 5 | 325 | 325 |
| 6 | 320 | 620 | 6 | 330 | 330 |
| 7 | 325 | 320 | 7 | 330 | 330 |
| 8 | 325 | 540 | 8 | 320 | 320 |
| 9 | 320 | 750 | 9 | 330 | 330 |
| 10 | 325 | 320 | 10 | 330 | 330 |
| 11 | 325 | 325 | 11 | 330 | 330 |
| 12 | 330 | 560 | 12 | 330 | 330 |
| 13 | 325 | 630 | 13 | 330 | 330 |
| 14 | 320 | 680 | 14 | 320 | 320 |
| 15 | 325 | 320 | 15 | 325 | 325 |
| 16 | 325 | 325 | 16 | 320 | 320 |
| 17 | 325 | 630 | 17 | 325 | 325 |
| 18 | 320 | 330 | 18 | 325 | 325 |
| 19 | 310 | 310 | 19 | 320 | 320 |
| 20 | 325 | 750 + | 20 | 325 | 325 |
| 21 | 325 | 325 | | | 74.7 |
| 22 | 320 | 560 | | | |
| 23 | 320 | 750+ | | | |
| 24 | 325 | 600 | | | |
| 25 | 325 | 750+ | | | |
| 26 | 330 | 330 | | | |
| 27 | 330 | 750 + | | | |
| 28 | 330 | 320 | | | |
| 29 | 325 | 630 | | | |

% rejects 18/29 = 62% % rejects = 0/20 = 0%

PROJECT IX IMPROVED EXHAUST FIXTURING

The purpose of this project is to further improve alignment and concentricity of the tube beyond that attained in Project I.

Improvements made in Project I were attained by reductions in tolerences of tube parts. The basic limitation in making this improvement is the fixtures used to hold the tube's parts during the exhaust and sealing cycle. Present materials and design of fixtures are such that warping of the fixture takes place during exhaust.

Six possible improved designs have been fabricated and examined.

Prints of these exhaust fixtures are included in the appendix.

An alignment-assembly jig has been designed for use in conjunction with the exhaust fixtures. Upon investigation, the tungsten "spider" spring of designs #4, #5 and #6 proved to be extremely fragile and undesirable for production use. The molybdenum rocker washer of designs #2 and #4 produced a drain of heat at the grid, which caused very poor seals. Design #1 and #3 appear to show the most promise. The tungsten springs lost tension after several exhaust cycles; however, these designs have been returned to our equipment development operation for redesign of the tungsten springs for better hot strength. Upon return of these fixtures, sustained production will be run and concentricity measurements will be performed.

The alignment-assembly jig did not hold the base of the exhaust fixtures firmly enough when first tested. Slop in the holding of the exhaust fixture base would reflect itself in poor concentricity. This device has also been returned for redesign of the fixture which holds the base of the exhaust fixture. The redesigned alignment-assembly jig should be ready as soon or before the redesigned exhaust fixtures.

PROJECT X EXTENDED LIFE TEST AND TUBE FAILURE ANALYSIS

This contract and the present MIL specification on the JAN 6299 specify 1,000 hour life test. It is well recognized that much longer life than 1,000 hours of operation is desired in Signal Corps equipments. The purpose of this project is to determine the life results of the improved tube to 5,000 hours and to determine the nature of any resulting failures so that information can be made available for possible tube or manufacturing improvements. These data will provide reliability and failure rate data on the tube for 5,000 hours.

Thirty tubes will be equally divided into a control sample and a test sample. During life test, there will be reading periods of 100 hours between 0 and 1,000 hours and reading periods of 250 hours from 1,000 to 5,000 hours. At each reading the values of transconductance, noise figure, amplification factor, grid voltage, and capacitance will be recorded.

CONCLUSIONS

Project I, II and IV are 100% complete.

Project III is not on schedule due to delays incurred at Scranton. Since transfer to Owensboro, the revised schedule has been met.

Tests performed on Project VI indicated that tubes must have hard solder anodes to withstand 225°C anode seal temperature consistently.

The mass spectrometric gas content analysis has shown that the majority of tubes failing SCS-90 humidity test do so because of the introduction of hydrogen into the tube. The source of the hydrogen has not been isolated.

Project IX has been delayed several weeks due to the necessity to redesign the springs of the exhaust fixtures to increase the hot strength. This project should be completed in time to include it in the 24 engineering samples to be constructed in February.

No work was scheduled in this interval on Project ${\tt V}$ and Project ${\tt X}$.

A project schedule is included on the following page with the progress indicated on each project.

| | | | | :: | | | | | | 11 | | | | | | | | | | | | | | | | | | | | | | | | | + | | | | | | | | | | | | | | | | |
|--|----------|----------------|------------|---------------------|----------|---|-----|---|----------|-------------|-----|---|---|-----------------------|----------------|-----|-----------------|---------------------------|---|-------|---|----------|---|-----|-------|-------------|---|----|-----|-----|----|----|--------|----|------|-----|---|--------------|---|----------|---|---|-----------|-----|----------|----|---|-----|-----|----|---------------------------------------|
| | | | | | | | | | | | | | | | | III | | | | | | | | | | | | ╫ | ₩ | # | | | ₩ | | i | | | | | | | 1 | H | | +; | | | | | | |
| | | | | | | | 7 | | | | | | | | | | | | | | | | | | | \parallel | | | | | | | | | | | | | | | Ë | | | | | | | | 13 | | |
| | | | | | | | | | | | | | | i B | | | | | | | | | | | | ! | | | | | | | Ш | | | | | | | | 1 | | | | | | | 3 | 9: | | |
| | | | | | | | | | | | | 4 | Ç | Ų. | | | | | | | | | H | | Н | | | | | | | | | | | | | | | | 1 | 1 | | | # | 11 | | 111 | 111 | 4 | _ |
| | | | | | | | | | | \parallel | | | | | | | | | | + | # | | | | | | H | | | | | | | | | | | | ₩ | | | | | | | | | | | 1 | O |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | iii | | | | | | | | | | | 1 2 | 3 | 2 | | | | # | ا_ ال |
| | | | | | | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | 1 | ~ |
| | | | | | | | | | | | | | | | | H | | † . | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | د |
| | | | | | | | 1 | | <u>H</u> | | | | | | | | | | | riri. | | | - | | | | | | | | | | 3 | | | 1 | | | | | | | | | | | | | | Ħ | _ |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | 2 |
| | | | | | | | 95 | | | | | | | | | | | | | 11 | | | | | | | | | | ij. | | | | į, | 1 | | | | | | | | | | | | | | | | = |
| | | | | | | | | | | | 111 | | | | | | | | | | | | | | | | | | | | | | 1 | i | Ħ | iii | | | | | | | | | E | 1 | | | | | 7 |
| | | | | | | | ni. | | 1:: | | | | 1 | | | | :: | | - | | | | | | | | | | | | | | | | | | | | | | | | | | <u>.</u> | | 4 | 3 | | | ٢. |
| | + | | ::: | ::: <u> </u> ::: | | | | | | | | | | | | | :: | | :: | :: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | ~ |
| | 1 | | | | | | | | | | | | | | | iii | # | | | 1 | | | | | | | | | | | | | H | | | | | | | | | | H | | | | | | | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| | | | | | | | | | | | | | | | | | | | :::: | | | | | | | | | | | | | | | | | | | # | | ia Ia | | | | | | | | | | | 1 |
| | | | | | | | 7 | | | | | | | | H | | # | | ::::::::::::::::::::::::::::::::::::::: | | | ij | | ## | | | | | | | # | ij | | | | | | 7 | | | | | Щ | | | | ░ | Ш | | | ~ |
| | 11: 3 | 1 | | | | | | | | | | | | | | | :: | ! : : : : | | | | | | | | | | :: | | - | ## | | | | ! E: | | | | | H | | | | | | | | | | | c |
| | | - - | | | | : | | | | | | | | | ! : : ! : : | | <u>::</u> :: | | ::: | | | | | | | 11 | | | | | ₩ | | | | 111 | | | ::: <u>:</u> | | | | | | | | | | | | | - |
| | 4: | T L | | | | | | | | | | | | | | | H | | :: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | 114 | 44 | - |
| | - | 14.4 | | | | | E | | | | 17 | | | H | | | 1: | | ::: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | 1 | | | |
| | | | | | | | | | | | | | | | | | ii E | | i: | | | * | | | - | | | | | | , | | Ý | | | | | | | 1 | | | | | 5 | | | | | | 0 |
| | | | ::: | | ::: | | | | | | | | | # | 11: | | | | 11 | 11 | | | | | è | 4) 11 | | 1. | | | | | | | | | | | | | | |) | | | 2 | | | | | ŭ |
| | | | | | | | | | | | | | | H | | | 11 | | | 11 | | | | | 1 4.4 | Ħ | | | | | ## | | | | | | | | | | | | | | | H | | # | | | , |
| | | | | | | | | | | | | | | | | e. | i | | | | | | | | | L | | | | | | | | | | Щ | | | | | | | | | | K | | | | | 7 |
| | | | ::: ::: | | | | | Ш | | | | | | , | | 111 | | | Į. | | | | | E. | i | 1 | | Ĭ | | Ì | | | 1 | | | | | | | H | | | | | | | | | | | - |
| | | | <u> </u> | | | | | | | | | | | | H | L L | 4 | | | Ei. | | | | 140 | | 31 | | | | | | Щ | | | | | | | | | | | | | | | | | | - | ~ |
| | | | | | ij | | | | | | | | | # | 1 | | | | | | | | | | Ī | | | | Fil | | | | H H | | H | | | | | | | | | | | | | | | | 0 |
| | | | | | | | | | | | | | | | | | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | 2 |
| | | | H | | Ħ | | # | | | | | | | | | | | | | | | | | | | | | | | | | | | | | 1 | | | | | | | | | | | | | | | |
| | | | | | <u> </u> | | | | | | | | | | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | # | = |
| | # | <u>: . : :</u> | | | | | 11 | | | ::: | | # | | $\parallel \parallel$ | | | | | | | | | | | | | | | | | # | | # | | | | | | | | | | | | | | | | | | ŋ |
| | | | | | Ħ | | | # | | | | | | \parallel | | Ħ | # | | | | | | | Ħ | | | | | | | ₩ | | | | H | | | | | | | | | H | | | | | | | х ~ |
| | | | H | | | | | | | | | | | ║ | | | # | | | | | | | | | | | | | | ░ | | | | | | | | | | | | | | | | | | | | ح |
| | | Ш | Ш | ∭ | I | | ₩ | # | | ▦ | ▦ | # | | Ш | Ш | Ш | Ш | Щ | | Ш | Ш | Ш | | Ш | | | Ш | | ▦ | | ₩ | Ш | | | Ш | Ш | Ш | | | ▦ | ▦ | ▦ | Щ | Ш | Ш | Ш | Ш | | Ш | Ħ | ~ |

PROGRAM FOR THE NEXT INTERVAL

Project I - 100% complete

Project II - 100% complete

Project III - Run sustained sealing and exhaust cycles with
the present processing duplicated and correlate
this with seal quality. Connect two exhaust
sets to one temperature controller and make the
necessary adjustment for uniform results.

Project IV - 100% complete

Project V - Build tubes and finalize cathode foil size to give optimum cathode temperature. Determine best method to read cathode temperature.

Project VI - Continue to investigate gold plating preservation under high temperature. Test tubes with hard solder anodes and hard solder preseals to check survival with present processing. Investigate improved processing for high temperature life.

Project VII - Test current production tubes and evaluate

efforts of temperature control at exhaust. Try

to isolate whether hydrogen failures are caused

by seal corrosion or base material corrosion.

Project VIII - Build 24 engineering samples to demonstrate the successful transfer of the facility to Owensboro.

Project IX - Evaluate the redesigned exhaust fixtures and modified alignment-assembly jig. Measure concentricity of tubes evaluated with those devices.

Project X - No work scheduled in the next quarter.

PUBLICATIONS, LECTURES, REPORTS AND CONFERENCES

PUBLICATIONS - None

LECTURES - None

REPORTS - Monthly Narrative Report No. 13

Development of an Improved JAN 6299

by D. L. Cook for the period from

September 1962 to October 1962.

Monthly Narrative Report No. 14

<u>Development of an Improved JAN 6299</u>

by D. L. Cook for the period from
October 1962 to November 1962.

Monthly Narrative Report No. 15

Development of an Improved JAN 6299

by D. L. Cook for the period from

November 1962 to December 1962.

Monthly Narrative Report No. 16

Development of an Improved JAN 6299

by D. L. Cook for the period from

December 1962 to January 1963.

CONFERENCES - 1. Organization and personnel present:

USASSA

L. Coblentz

General Electric Company

A. T. Tomko

J. T. Duncan

E. L. Davis

D. L. Cook

Place and Date:

General Electric Company Receiving Tube Department Owensboro, Kentucky

September 12, 1962

CONFERENCES - Subject:

Review status of the contact and discuss the affects of the transfer of Production Engineering measures Contract No. DA-36-039SC-85953 (Type 6299) to Owensboro, Kentucky.

2. Organization and personnel present:

USASSA

L. Coblentz

General Electric Company

A. T. Tomko J

J. N. McClanahan

E. L. Davis

D. L. Cook

Place and Date:

General Blectric Company 316 E. Ninth Street Owensboro, Kentucky

January 15, 1963

Subject:

Review status of the contract.

PERSONNEL

Listed below are the technical personnel who participated in the program during this reporting period. The approximate man-hours each spent is entered opposite his name. A biographical sketch of Mr. J. N. McClanahan appears in the Appendix.

| A. T. Tomko | 10 Hours |
|------------------|----------|
| P. Kirby | 19 Hours |
| B. I. Grady, Jr. | 28 Hours |
| J. N. McClanahan | 51 Hours |
| D. L. Cook | 98 Hours |

Submitted by:

D. L. Cook

Manufacturing Engineering Receiving Tube Department

Approved by:

A. T. Tomko, Manager Production Engineering Receiving Tube Department

APPENDIX

Personnel Biography


J. N. McClanahan

Mr. McClanahan, a native of Kansas, received his Bachelor's Degree in Electrical Engineering from the University of Kansas in June of 1962.


Upon graduation, he joined the Planar and Thyratron Section as a Process Control Engineer where he is working primarily on the Miniature Ceramic Lighthouse.


APPENDIX

Prints



| ſ | REV NO. | · | TITLE | ERAL 🎉 | | | CONT ON SHEET | | SH NO. |
|---|----------------|-------------|---|------------|------------|--------------|---------------|----------|--------|
| | | | DE | IGN # | 2 – E | XHAUST | FIXTURE | | |
| | CONT ON SHEET | SH NO. | FIRST MADE FO | | | 6299 | | | _ |
| + | | 11 | | | | | | | |
| | | • | | • | | | | | |
| | | | | | | | | | |
| | | | | - | | | | | |
| | | | ļ | | | | • • | ŀ | |
| | , | | | | | | | •. | |
| + | | • | | = | • • | | | | |
| | | | | | | | | | |
| | | گم | | E III | | <u> </u> | | | |
| | | 7 | | FI T | | · / TUN | BSTEN SPR | RING | |
| | | # | | / | .# | , | | | |
| | | 4 | | | ! ! | | | | |
| | | <u>م</u> | <u> </u> | (| | | | | |
| | | | | | | 20 | | | |
| | • | 1 | | | | | • | • | |
| + | | | | | | | | | |
| | | 1 | | | ı I | - N | 40LYBDENU: | M WA | SHER |
| | | , | | | | | , | | |
| • | | | | | | | | 1 ' | |
| | | ŀ | U | FILL | j | • | | | |
| | | | • | | | | | • | |
| | | | | | | | | | |
| | | | | | | | , | , | |
| + | | | UNLESS OTHERWISE SPECIFIED USE | APPLIED PR | RACTICES | SURFACES | FRACTIONS + | DECIMALS | |
| 1 | | | USE | | PEVISION | | <u> -</u> | | PRINTS |
| | | | • | _ | REVISION | 7 | · | _ ' | -KINIS |
| | | | | | | | | | - |
| | | | | | | | | - | _ |
| | | | | | | | | | |
| | | | | | | | | | |
| + | | | | | | | · | | |
| | MADE BY L.KERS | STEN | APPROVALS | | | DIV OR | | | |





| | | | ERAL 🛞 ELE | | CONT ON SHEET | SH NO. |
|---------------|----------|---|-----------------|---|-----------------------------------|-----------------|
| REY NO. | | TITLE | : (1 | 6 | • | ••• |
| | | | SIGN # 5- | EXHAUST | FIXTURE | |
| CONT ON SHEET | SH NO. | FIRST MADE FO | R | G.L. 629 | 9 | |
| | | | · | | · · · · · · · · · · · · · · · · · | |
| | | | • | ٠. | | |
| | | | | | | |
| | • | | | | • | |
| | | | | | | • |
| | | | · ' | • | | |
| | | Į; | • | | • | |
| | | Į. | | | | |
| | | ľ | 1 | | | • |
| | | · [| 4 | | • | • |
| | | ĺ | 1 | | | • |
| | | 1 | 1 | | | |
| | | l | 1 | | | |
| | | | 100 | | į. | |
| | 7 | | = | = | | • • |
| | | | | | • | |
| | 4 | <u>'</u> | | | • | |
| | ئىل ا | 1 | Ţ, | | | • •• |
| | | | | | | |
| | 1 | | | | | |
| | i | | | 1 | | •, |
| | | | | | | |
| | | <u> </u> | ::://// | | • | |
| | 1 | '[] | | | | |
| | | | 1 | ļ | | |
| | | " | === | | | |
| | | UNLESS | APPLIED PRACTIC | S SURFACES | | ACHINED DIMENSI |
| | • | UNLESS OTHERWISE SPECIFIED USE | | | + + + | CIMALS AN |
| | | USE | P.E.\ | risions | 1- 1- | PRINTS 1 |
| | | • | XE. | T | | |
| | | | | | | |
| | | | | | • | |
| | | | | | • | |
| | | | | | | |
| | | | • | | | |
| MADE BY | | APPROVALS | | | | |
| ISSUED | | | | DIV (| PT | |
| | | 1 | 1 ' | LOCATH | ON CONT ON SHEET | 8H NO. |

| | GENERAL & ELECTRIC | | | | CONT ON SHEET | EM NO. |
|---|--------------------|-----------|--|--------------------------|---------------------|---------------|
| | REV NO. | <u></u> | TITLE DESIGN | # 6- EXHAUST G.L. 629 | FIXTURE | |
| + | CONT ON SHEET | SH NO. | FIRST MADE FOR | 3,1 00 / | | |
| | | | | , | | |
| | | | | • | | |
| | | | السا | , | | |
| | | | | | | · |
| + | | | 1 1 | • | | |
| | | | \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ | • | • | , |
| | | | | • | | |
| | | | <u>[</u> | | | |
| | | | | • | | |
| | | | | TE BA | | |
| | | | | | | |
| + | | | | 1 | • | |
| | | i | | 1 1 | | |
| | | | | | | |
| | | | | | | |
| | | 1 | | # | | |
| | · | | | • | | |
| | | | UNLESS APPLIE | D PRACTICES SURFACE | | MACHINED DIME |
| + | | | SPECIFIED USE | | + + | |
| | | | | REVISIONS | , · | PRINT |
| | | | | , | , | |
| | | | | | | |
| | | | | | | |
| + | | | | | | |
| | MADE BY | | APPROVALS | | OR REPT | |
| | 1 | | 1 | LOCAT | 13348 NO THOO NOT | SH N |